

Contents

1	Introduction	1
1.1	Motivation	1
1.2	Background and state of the art	3
1.3	Novel contributions	15
1.4	Organization	16
2	Safety-related Systems (SRSs)	19
2.1	Preliminaries	19
2.2	Failure	21
2.2.1	Definition	21
2.2.2	Random hardware failure vs. systematic failure	21
2.2.3	Failure modes	24
2.3	Maintenance	28
2.3.1	Preliminaries	28
2.3.2	Corrective maintenance	29
2.3.3	Preventive maintenance	30
2.4	Figures of merit	32
2.4.1	Preliminaries	32
2.4.2	Reliability and frequency of a dangerous failure (PFH)	32
2.4.3	Availability and probability of dangerous failure on demand (PFD)	33
3	Modeling via Stochastic and Deterministic Timed Automata (SDTAs)	37
3.1	Preliminaries	37
3.2	SDTA definition	38
3.2.1	Preliminaries	38
3.2.2	Deterministic timed events	38
3.2.3	Exponential stochastic timed events	39
3.2.4	Model of an SRS	40
3.3	Procedure to model SRS with multiple elements	47
3.3.1	Preliminaries	47
3.3.2	The SRS element	47

3.3.3	Parallel composition	50
3.3.4	Dependent SRS elements	51
3.3.5	SRS elements with common-cause failures	52
3.4	Discussion on SDTAs	54
4	Probabilistic evaluation of the SDTAs via Multi-phase Continuous-time Markov Chains (MP-CMCs)	57
4.1	Preliminaries	57
4.2	MP-CMC definition	57
4.3	SDTA transformation into MP-CMC	61
4.4	Preventive maintenance (PM) plans and strategies	65
4.4.1	Preliminaries	65
4.4.2	Definition of PM plan	65
4.4.3	Restrictions on PM plans	65
4.4.4	Definition of PM strategies	68
5	Model analysis and validation	71
5.1	Preliminaries	71
5.2	Analyzed models	71
5.2.1	Preliminaries	71
5.2.2	One element model	73
5.2.3	Three element model	75
5.2.4	Results	76
5.3	Validation	78
5.3.1	Preliminaries	78
5.3.2	Model of Torres-Echeverría et al.	78
5.3.3	Model of Brissaud et al.	79
5.3.4	Model of IEC 61508	80
5.3.5	Results	80
5.4	Sensitivity analysis	86
5.4.1	Preliminaries	86
5.4.2	Theoretical framework	86
5.4.3	Results	88
6	Optimization of preventive maintenance plans	93
6.1	Preliminaries	93
6.2	Optimization problems	93
6.3	Optimization algorithm	94
6.3.1	Preliminaries	94
6.3.2	Nelder-Mead method	95

6.4	Heuristic approach to minimize the maximum PFD	98
6.5	Results	100
6.5.1	Preliminaries	100
6.5.2	Models without redundancy	102
6.5.3	Models with redundancy	106
6.5.4	Models with redundancy and common-cause failures	110
6.6	General conclusions	113
7	Summaries	117
7.1	Summary in English	117
7.2	Outlook	118
7.3	Extended summary in German – Kurzfassung in deutscher Sprache	119
A	Model of SRS element with reduced number of states	123
B	State classification of selected <i>MooN</i> element structures	127
C	Models of selected dependent SRS elements	129
D	Nomenclature	133
Bibliography		141
About the author		145